



Photo 1. Post-Tropical Storm Ivan: View of beach fill, standing on top of existing rock shoreline protection at appx. Sta. 100+00 looking east (tide: appx. 1.7' NAVD)



Photo 3. Pre-Hurricane Ivan: View of beach fill, standing on top of existing rock shoreline protection at appx. Sta. 100+00 looking east (tide: appx. 1.5' NAVD)



Photo 2. Post-Hurricane Ivan: View of beach fill, standing on top of existing rock shoreline protection at appx. Sta. 100+00 looking east (tide: appx. 1.3' NAVD)



Photo 4. Beginning of front dike erosion at appx Sta. 135+00 looking east



Photo 5. *Dune erosion at Sta. 195+00, looking east*



Photo 7. *Dune erosion at Sta. 199+00, looking west*



Photo 6. *Dune erosion at Sta. 199+00, looking east*



Photo 8. *Dune erosion at Sta. 206+00 (east end of project), looking west*



Photo 9. *View of back dike, standing at dock (Sta. 170+00) looking east (tide: appx. 1.5' NAVD)*